CHRONOS SAFETY GLASSES

Eyewear built by Mack.





AS/NZS 1337.1:2010 tested and approved for medium impact protection, marked by the letter "i" on the lens/lenses



ANTI-FOG -Coating for use in humid environments



UV PROTECTION

Protects eyes against harmful UV damage

OPTIONAL STRAP

Provides a more secure fit and convenient placement

PADDED ARMS

Soft TPR padded arms for superior comfort

DIALECTRIC MODEL

Metal free, no risk of electrical arcing around power lines or machinery

ANTI-SCRATCH

 Coating for durable protection against marking and dirt build up



LENS COLOURS







Clear

Smoke

Blue Mirror

CODE	LENS	COATINGS	BOX QTY	CARTON QTY
MKCHRONOSCR0000	Clear	Anti-scratch/Anti-fog	12	240
MKCHRONOSSM0000	Smoke	Anti-scratch/Anti-fog	12	240
MKCHRONOSBL0000	Blue Mirror	Anti-scratch/Anti-fog	12	240

CLEANING:

- Air blow to remove surface grit and wipe with soft cleaning cloth.
- Do not use solvents or abrasive cleaners.
- In case lens is wet, DO NOT wipe it. Pat dry with tissue and then wipe with soft cleaning cloth.

Australian Standard

AS/NZS 1337.1.2010 Lic. 1502 Made in Taiwan

APPLICATIONS

General Industry • Construction • Agriculture • Mining • Metal Work • Food Safe

CHRONOS GASKET SAFETY GLASSES

Eyewear built by Mack.





AS/NZS 1337.1:2010 tested and approved for medium impact protection, marked by the letter "I" on the lens/lenses



ANTI-FOG

Coating for use in humid environments

DIALECTRIC MODEL

Metal free, no risk of electrical arcing around power lines or machinery



UV PROTECTION

Protects eyes against harmful UV damage CLIP-ON FOAM GASKET movable easy click on/off

 Removable easy click on/off gasket for extra dust exclusion

OPTIONAL STRAP

Provides a more secure fit and convenient placement

PADDED ARMS

Soft TPR padded arms for superior comfort

ANTI-SCRATCH

Coating for durable protection against marking and dirt build up



LENS COLOURS





Clear

Smoke

CODE	LENS	COATINGS	BOX QTY	CARTON QTY
MKCHRONOSSC0000	Clear With Foam Gasket	Anti-scratch/Anti-fog	12	240
MKCHRONOSSS0000	Smoke With Foam Gasket	Anti-scratch/Anti-fog	12	240

CLEANING:

- Air blow to remove surface grit and wipe with soft cleaning cloth.
- Do not use solvents or abrasive cleaners.
- In case lens is wet, DO NOT wipe it. Pat dry with tissue and then wipe with soft cleaning cloth.



AS/NZS 1337.1.2010 Lic. 1502 Made in Taiwan

APPLICATIONS

General Industry • Construction • Agriculture • Mining • Metal Work • Food Safe